

# bosal

## Инструкция по монтажу тягово-цепного устройства шарового типа 3957 А для автомобилей Ford Galaxy

: Ford Galaxy	2006-...
	1500
	75
	16.45





462800,

18  
: (35363) 7-05-06  
/ : (35363) 7-13-20  
(495) 799-13-46  
[www.bosal-autoflex.ru](http://www.bosal-autoflex.ru)  
[www.bosal.com](http://www.bosal.com)

« - »:  
" (8182) 22-48-15  
" 8(8442) 98-74-98  
" 8(343) 379-39-89, 373-42-73  
" 8(343) 26-88-308  
" 8(3952) 710-194  
" 8(495) 777-54-59  
" 8(495) 745-79-11  
" 8(495) 788-95-97  
" 8(495) 720-51-03  
" 8(3532) 57-99-85  
" 8-905-899-5012  
" 8(383) 291-59-60  
" 8(831) 279-53-24  
" 8(3422) 98-27-20  
" 8(342) 220-87-87  
" 8-927-002-90-06  
" 8(3462) 24-00-44  
" 8(3842) 21-14-76  
" 8-902-940-4151  
" 8(3452) 32-22-12, 41-52-62  
" 8-961-213-0278  
" 8-917-347-1700  
" 8(351) 269-44-75, 900-72-73  
" 8(3512) 773-76-91

41.55-2005.

«3» ( «c» «d». «b» 10 40, «e»



	1 .
	1 .
	1 .

12	1,25 /	2 .
10		2 .
12		4 .
10 ( )		6 .
10 40		6 .
12 1,25 75		2 .
		3 .
		2 .
VH 0840		1 .
		1 .
		1 .
		1 .
190		1 .
		1 .
		1 .